CERTIFICATE OF APPROPRIATENESS STAFF CHECKLIST

LOCATION: 912 Walker Avenue **HISTORIC DISTRICT:** College Hill

APPLICATION NO. 761

APPLICANT: James Cassell, Contractor **PROPERTY OWNER:** Laura Little **DATE RECEIVED:** May 9, 2006

DESCRIPTION OF WORK (from application)

"Remove the canopy on the roof over the Front Porch, there's no access to the canopy, and it is completely rotten. She is upgrading her home and it will be too expensive for her to rebuild."





